



Do not place the tripod in the center of the tower wall hole,
because the threaded bolt of the microphone is
not radially symmetric to the microphone circumference.



bat bioacoustic technology GmbH
Brunngasse 1
90610 Winkelhaid

Title:

Drilling Plan: Tower Microphone TM20